




Maintenance




Service - Cleaning filter - 150 c-c




Koninklijke Sphinx B.V.
Postbus 1019
NL 6201 BA Maastricht






Dismount - Freezing point



Installation/Service
38°C temp adjustment



Installation/Service
Limit temperature (Max hot)

